1 INSPECTIONS EXCLUDED FROM AAIP

Since the AAIP inspection program is not intended to prescribe maintenance functions, the following items will be tracked separately in the aircraft status report.

A. Hand-held Fire Extinguishers

B. Static System and Altitude Reporting System per 14 CFR 91.411.

C. ATC Transponder Test and Inspections per 14 CFR 91.413.

D. Inspect Pitot-Static System per 14 CFR 91.411/413

E. 36 Month Hydrostatic Retest of Emergency Floatation Gas Cylinder per AA-ICA407-11

F. 1500 Hour Mast Overhaul BHT-206L Series MM-1 Table 5-40

G. 2250 Hour / 60 Month Transmission Overhaul BHT-206L Series MM-1 Table 5-41

H. 3000 Hour Tail Rotor Gearbox Overhaul BHT-206L Series MM-1 Table 5-42

I. 300 Hour N1 and N2 Tach Gen Spline Insp/lube BHT-206L Series MM-1 Para 5-23 Item 16

J. Engine Wash – Rolls-Royce M250-C30 Series MM 72-30-00 Para 5.B

K. Freewheeling Unit 60 Month Insp BHT-206L Series MM-1 Para 5-36

L. A1202 1200 Hr Tailboom - Deleted. Now tracked as AD2002-25-07

M. Battery Recondition I/A/W BHT-ALL-SPM

N. 150 Fuel Nozzle Cleaning/Inspection - Rolls-Royce M250-C30 Series MM 73-10-03 Para 5.B