C 1700NT Calendar Inspection every twelve months.

Corrections needed.

I thought it would be helpful to have the bridal cable tensions available in the inspection with the reference.

1. 5.1.4: Aileron Servo Bridal Cable Tensions. Can we add, 15lbs +2lbs -0lbs. Ref 22-10-12 table 1

2. 5.2.5: Elevator Servo Bridal Cable Tensions. Can we add, 25lbs +5lbs -0lbs. Ref 22-10-12 table 1

3. 5.3.4: Rudder Servo Bridal Cable Tensions. Can we add, 25lbs +5lbs -0lbs. Ref 22-10-12 table 1

4. 5.4.4: Pitch Trim Servo Bridal Cable Tension. Can we add, 15lbs +2lbs -0lbs. Ref 22-20-00 table 2

5. C 1700.6 23 – Communications 6.1: Pressure test coupler. Remove this. We do not have High Frequency Radio installed.

6. C 1700.11 34 – Navigations, 11.1, "Standby Compass Swing." Not sure if we want to keep this, or remove this task from the CALM. This is on the CALM as a Calendar inspection every 12 months. I'm fine with either one.